

SAP ABAP table S163 {Quantitative Inspection Result: Vendor}

S163
<u>MANDT</u> [CLNT (3)]
<u>SSOUR</u> [CHAR (4)]
<u>VRGIO</u> [CHAR (3)]
<u>SPMON</u> [NUMC (6)]
<u>SPTAG</u> [DATS (8)]
<u>SPWOC</u> [NUMC (6)]
<u>SPBUP</u> [NUMC (6)]
<u>LIFNR</u> [CHAR (10)]
<u>MATNR</u> [CHAR (18)]
<u>PRPLATZWKR</u> [CHAR (4)]
<u>PRPLATZ</u> [CHAR (8)]
<u>WERKSTPRUE</u> [CHAR (12)]
<u>PLGRPLTYP</u> [CHAR (9)]
<u>PPLNKN</u> [NUMC (8)]
<u>MERKNR</u> [NUMC (4)]
<u>WERK</u> [CHAR (4)]

LFA1
<u>MANDT</u> [CLNT (3)]
<u>LIFNR</u> [CHAR (10)]

MARA
<u>MANDT</u> [CLNT (3)]
<u>MATNR</u> [CHAR (18)]

T000
<u>MANDT</u> [CLNT (3)]

T001W
<u>MANDT</u> [CLNT (3)]
<u>WERKS</u> [CHAR (4)]

