


# SAP ABAP table S165 {Inspection Results (General): Customers}

| <b>S165</b>                   |
|-------------------------------|
| <u>MANDT</u> [CLNT (3)]       |
| <u>SSOUR</u> [CHAR (4)]       |
| <u>VRGIO</u> [CHAR (3)]       |
| <u>SPMON</u> [NUMC (6)]       |
| <u>SPTAG</u> [DATS (8)]       |
| <u>SPWOC</u> [NUMC (6)]       |
| <u>SPBUP</u> [NUMC (6)]       |
| <u>KUNNR</u> [CHAR (10)]      |
| <u>MATNR</u> [CHAR (18)]      |
| <u>PRPLATZWRK</u> [CHAR (4)]  |
| <u>PRPLATZ</u> [CHAR (8)]     |
| <u>WERKSTPRUE</u> [CHAR (12)] |
| <u>PLGRPLTYP</u> [CHAR (9)]   |
| <u>PPLNKN</u> [NUMC (8)]      |
| <u>MERKNR</u> [NUMC (4)]      |
| <u>WERK</u> [CHAR (4)]        |



| <b>KNA1</b>              |
|--------------------------|
| <u>MANDT</u> [CLNT (3)]  |
| <u>KUNNR</u> [CHAR (10)] |

| <b>MARA</b>              |
|--------------------------|
| <u>MANDT</u> [CLNT (3)]  |
| <u>MATNR</u> [CHAR (18)] |

| <b>T000</b>             |
|-------------------------|
| <u>MANDT</u> [CLNT (3)] |

| <b>T001W</b>            |
|-------------------------|
| <u>MANDT</u> [CLNT (3)] |
| <u>WERKS</u> [CHAR (4)] |